

**INSTRUCTION
AND SPARE PARTS
MANUAL**

MASCOT
COLCHESTER
MASCOT

8½" Centres

and

DOMINATION
COLCHESTER
DOMINATION

17" Swing

All-Geared Head Lathes

2nd EDITION

**THE COLCHESTER LATHE CO. LTD.
COLCHESTER · ESSEX · ENGLAND
Telephone No. - COLCHESTER 6351**

Instruction and Spare Parts Manual

for

8 $\frac{1}{2}$ " Centre MASCOT

and

17" Swing DOMINION

ALL-GEARED HEAD LATHES


When ordering Spares it is essential to state Size,
Style and Serial Number of Machine in addition
to Part Number and Description.

Size 8 $\frac{1}{2}$ " Type MAM 10 Serial No. 5-36850

Purchased From: Jessay Machine Tools Ltd.
Channel Islands.

8½" MASCOT and 17" DOMINION

All-Geared Head Lathes




INTRODUCTION

The Colchester Lathes are the result of almost half-a-century of concentration on the manufacture of lathes. The keynote of Colchester machines is efficiency combined with simplicity. Our lathes are to be found working in all corners of the world and while essentially precision tools intended for the production of accurate workpieces, their simple design, robust construction and simplified controls make them very suitable for tooling for production work. All castings are naturally aged for at least six months to avoid any possible future distortion. Jigs and special purpose machines are used extensively in our manufacturing operations to ensure interchangeability of components, and care is taken in all processes in all departments to ensure your satisfaction.

This Manual supplies specific information relative to the Colchester 8½" Mascot and Dominion 17" Swing Centre Lathes. A thorough understanding of the information contained in this handbook will aid in securing the most satisfactory operating results from your machine.

At the time of issue, this handbook is completely up-to-date. However, improvements in design are continuously being made and it is possible that some information included in this book may vary from the machine delivered to you. This indicates that design changes have been made so that the machine will better fulfil your needs, and we therefore reserve the right to alter the design or specification at any time without notice.

ONE HANDBOOK IS ISSUED FREE WITH EACH MACHINE
ADDITIONAL COPIES CAN BE SUPPLIED AT 5/- EACH



The Headstock

DO NOT CHANGE SPEED WHILE RUNNING					
SPINDLE SPEEDS			PULLEY 590 R.P.M.		
LEVERS ON TOP					
LEVER AT FRONT		600	415	270	180
		125	87	56	37
OIL ALL BEARINGS REGULARLY THROUGH LUBRICATORS WITH SHELL TELLUS OIL 41					
KEEP LEVEL OF OIL TO MARK ON SIGHT GLASS					
THE COLCHESTER LATHE CO LTD ENGLAND					

Speed Change Chart

Alternative Spindle Speeds:—25 to 410 r.p.m.

THE ALL-GEARED HEADSTOCK

The Headstock forms a totally enclosed oil bath and provides eight spindle speeds (as shown on the Speed Change Chart opposite) from an input drive pulley speed of 590 R.P.M. This is accomplished through two high tensile heat treated shafts, carried in phosphor bronze bearings, and carrying gears of similar quality and operated, for speed selection, by means of two hand levers on top and one in front of the Headstock. The mechanism is of simple and robust design and will be readily understood by reference to the Headstock illustration. The main spindle is precision finished, from a heat treated high tensile steel forging and is carried on the latest type anti-friction bearings.

The front end of the spindle is carried on Gamet Super High Precision low angle double row cylindrical taper roller bearings of exceptional accuracy, specially manufactured to our requirements; the rear end of the spindle being carried on a single row taper roller bearing of similar design.

Another hand lever on the front of the headstock permits the leadscrew and feedshaft direction of rotation to be reversed.

The red control lever on the front of the headstock controls the running of the machine through an air break starting switch and a mechanical brake. This starting switch incorporates a no-volt release. In the case of an electrical supply failure, the machine can only be re-started by moving the control lever to the off position and then re-starting in the normal way.

It is necessary from time to time to check that the no-volt release is working correctly. This can be done by switching the motor off from the control panel, moving the red control lever into the starting position and switching the motor on again. If the machine starts up the no-volt release is not working correctly and an adjustment should be made. This is easily accomplished by releasing the lock nut underneath the switch lever at the back of the machine and unscrewing the stud sufficiently to allow it to operate satisfactorily. Finally, tighten lock nut.

When this lever is moved in the direction of the tailstock the motor starts up, and is cut out when the lever is returned, to its upright and off position. Pressure applied to the lever in the reverse direction operates an expanding brake in the drive pulley which stops the spindle instantaneously. This arrangement gives very rapid and sensitive control of the machine.

To enable instantaneous braking to be applied, use is made of the American Long Taper Key Drive type spindle nose to L.2. Standard, and the hole through the spindle is $3\frac{1}{8}$ " diameter (to pass 3" dia. bar).

ADJUSTMENTS

Spindle bearings are of such design and accuracy that they are correctly adjusted under cutting conditions before leaving our Works and therefore should give long service before any adjustment becomes necessary. The rear bearing is so designed that no adjustment is necessary, this being provided for by the spring loading of the bearing which gives constant pressure.

Should the removal of the main spindle or headstock shafts become necessary at any time, the following sequence of operations is recommended:

REMOVAL OF MAIN SPINDLE

1. Drain oil.
2. Remove end guard.
3. Remove top cover (Taking care not to damage gasket).
4. Remove six Cap head screws in rear bearing cover.
5. Remove rear bearing cover.
6. Remove grubscrew from collar on end of spindle.
7. Unscrew collar.
8. Remove six Cap head screws from front bearing.
9. Strike rear end of Spindle sharply with a wood or lead mallet or hammer.
10. Remove spindle complete with front bearing assembly, taking care not to damage gasket.
11. Remove main spindle gears, large clutch gear keep and back bearing inside race.
12. Reassemble in reverse order.

REMOVAL OF REAR END BEARINGS


1. Remove six Cap screws holding inside bearing cover.
2. Remove cover.
3. Tap out Bearing with usual care and precautions against damage.

REMOVAL OF INTERMEDIATE SHAFT

1. Remove Bridge Piece by unscrewing four $\frac{3}{8}$ " Counter-sunk screws.
2. Remove Grub Screw in Driving Shaft Collar and draw out shaft and pulley together.
3. Remove collar and gears.
4. Remove brake assembly.
5. Remove four Cap Head screws from flanged bearing and draw out bearing.
6. Remove grub screws in Intermediate Shaft gear.
7. Remove brass screw holding Intermediate Shaft bearing.
8. Insert Jacking Screw in Intermediate Shaft bearing at front end and withdraw. Next insert Jacking Screw in end of shaft and draw out.
9. Remove gears.

REMOVAL OF DRIVING SHAFT

As instructions 1, 2 and 3 for intermediate shaft.



The Quick Change Feed Box

MASCOT MADE BY COLCHESTER LATHE CO. LTD COLCHESTER ENGLAND	LEVERS	ENGLISH - THREADS PER INCH						METRIC - PITCH IN M/M		
		SLIDING FEEDS IN THOUSANDTHS — SURFACING 1/2 SLIDING								
	D B	60 003	56 0035	52 0038	48 0041	44 0045	40 005	38 0052	36 0055	32 0062
	C B	30 006	28 007	26 0075	24 008	22 009	20 010	19 0103	18 011	16 0125
D A	15 013	14 014	13 015	12 017	11 018	10 020	9 1/2 021	9 022	8 025	
C A	7 1/2 026	7 028	6 1/2 030	6 033	5 1/2 036	5 040	4 3/4 041	4 1/2 044	4 050	

English Screw Cutting Chart

DOMINION MADE BY COLCHESTER LATHE CO. LTD COLCHESTER ENGLAND	LEVERS	THREADS PER INCH								
		SLIDING FEEDS IN THOUSANDTHS — SURFACING 1/2 SLIDING								
	D B	56 0035	52 0038	48 0041	46 0043	44 0045	40 005	38 0052	36 0055	32 0062
	C B	28 007	26 0075	24 008	23 0085	22 009	20 010	19 0103	18 011	16 0125
D A	14 014	13 015	12 017	11 1/2 017	11 018	10 020	9 1/2 021	9 022	8 025	
C A	7 028	6 1/2 030	6 033	5 3/4 035	5 1/2 036	5 040	4 3/4 041	4 1/2 044	4 050	

Dominion Screw Cutting Chart

MASCOT QUICK CHANGE FEED BOX

The feed box forms a totally enclosed oil bath and provides 36 Whitworth thread pitches, 11 Metric pitches and 36 feeds (as shown on the Screw Cutting and Feed Charts). Changes are accomplished, without any wheel changes being necessary, through a train of heat treated gears carried on high tensile heat treated splined shafts.

The feed box, while simple, is very effective and robust and is controlled by means of three selection levers situated at the front of the box. A fourth lever provides for the selection of either English or metric trains of gears and controls the leadscrew disengagement.

Should the removal of any part of the Feed Box become necessary, the dismantling procedure will be clear if the oil is drained, the tumbler arm removed and the front cover taken off, but in case it is necessary to take down the tumbler shaft the following sequence of operations is recommended.


REMOVAL OF TUMBLER SHAFT

1. Drain oil.
2. Remove Tumbler Arm plug.
3. Take out $\frac{1}{4}$ " Grub screw.
4. Release grip of arm and remove.
5. Remove front cover.
6. Remove Tumbler Gear.
7. Remove circlip.
8. Remove three $\frac{3}{16}$ " Cap screws in flanged bearing.
9. Slide shaft out in direction of tailstock.
10. Withdraw flanged bearing.
11. Remove tumbler bearing.

Formula to obtain Change Gears for special threads

Thread required to be cut

$$\frac{3 \times Y}{14T} = \frac{\text{Drivers}}{\text{Driven}}$$



X =

HOLE IN FEED BOX

T = THREADS PER INCH TO BE CUT.

$$Y = \begin{cases} 1 = \text{LEVER AC.} \\ 2 = \text{LEVER AD.} \\ 4 = \text{LEVER BC.} \\ 8 = \text{LEVER BD.} \end{cases}$$

EXAMPLE: 21 threads required to be cut.

$$\frac{3 \times 28 \times 2}{14 \times 21} = \frac{4}{7} = \frac{24 \text{ Driver}}{42 \text{ Driven}}$$

DOMINION QUICK CHANGE FEED BOX

The feed box forms a totally enclosed oil bath and provides 36 thread pitches and 36 feeds (as shown on the Screw Cutting and Feed Charts). Changes are accomplished, without any wheel changes being necessary, through a train of heat treated gears carried on high tensile heat treated splined shafts running in phosphor bronze bearings.

The feed box, while simple, is very effective and robust, and is controlled by means of three selection levers at the front of the box. A fourth lever operates the leadscrew disengagement.

Change wheels for cutting Metric pitches are only furnished at extra cost.


Should the removal of any part of the feed box become necessary, the dismantling procedure will be clear if the oil is drained,

the tumbler arm removed and the front cover taken off, but in case it is necessary to take down the tumbler shaft the following sequence of operations is recommended:

Removal of Tumbler Shaft

1. Drain oil.
2. Remove Tumbler Arm plug.
3. Take out $\frac{1}{4}$ " grub screw.
4. Release grip of arm and remove.
5. Remove front cover.
6. Remove tumbler gear.
7. Remove circlip.
8. Remove three $\frac{1}{8}$ " Cap screws in flanged bearing.
9. Slide shaft out in direction of tailstock.
10. Withdraw flanged bearing.
11. Remove tumbler bearing.

FORMULA TO OBTAIN GEARS FOR SPECIAL THREADS



T = THREADS PER INCH TO BE CUT.

- Y ...
- 1 = LEVER AC.
 - 2 = LEVER AD.
 - 4 = LEVER BC.
 - 8 = LEVER BD.

$$\text{Thread to be cut} = 3 \times Y \quad \frac{\text{Driver}}{14 T \quad \text{Driven}}$$

EXAMPLE

21 threads required to be cut

$$= \frac{3 \times 28 \times 2}{14 \times 21} = \frac{4}{7} = \frac{24 \text{ Driver}}{42 \text{ Driven}}$$


TABLE OF METRIC PITCHES							
PITCH M/M	LEVER	LEVER	DRIVER	DRIVEN	DRIVER	DRIVEN	HOLE
.5	B	D	36	127	120	42	G
.6	"	"	36	"	"	"	D
.7	"	"	42	"	"	"	"
.75	"	"	36	"	"	"	A
.8	"	"	36	"	"	35	B
.9	B	C	27	"	"	42	D
1	"	"	36	"	"	"	G
1.25	"	"	30	"	"	"	A
1.5	"	"	36	"	"	"	"
1.75	"	"	42	"	"	"	"
2	A	D	36	"	"	"	G
2.5	"	"	30	"	"	"	A
3	"	"	36	"	"	"	"
3.5	"	"	42	"	"	"	"
4	A	C	36	"	"	"	G
4.5	"	"	27	"	"	"	A
5	"	"	30	"	"	"	"
5.5	"	"	33	"	"	"	"
6	"	"	36	"	"	"	"
7	"	"	42	"	"	"	"

METRIC PITCHES


By employing special changewheels in the end train a range of metric threads may be obtained between .5 mm. and 7 mm. Pitch. The table opposite gives all the information required to enable the more usual pitches to be cut.

NOTE:—When cutting metric threads it is essential to follow the instructions given on page 11 under the heading SADDLE.

MASCOT




The Saddle




The Apron

DOMINION



Saddle



Apron

SADDLE

The Saddle, of adequate proportions, is mounted on vee and flat surfaces on the bed, is of the boring type on 8½" and American winged type on 17" lathes and fitted with a very robust compound slide.

The Saddle is secured to the bed by means of keeps in front and rear and can be locked on the bed at any position. All surfaces are precision machined. Large diameter micrometer dials reading in .001" are fitted to both slides and can be set to zero and clamped for easy operation. Operating screws and slides are covered in all positions. A triangular Tool Plate Clamp and an American pillar type toolpost is fitted as standard on the 8½" and 17" models respectively but special automatic indexing square turrets can be supplied at extra cost.

When the Colchester Coolant unit is ordered, the coolant supply pipe is bolted to the back of the carriage at the tailstock end, and moves along the bed with the carriage. The supply pipe is only furnished with the coolant unit.

The standard tool size for the MASCOT is 1¼" x 1¼" and for the DOMINION ⅝" x 1⅜".

The cross slide is radially graduated 180° a side for easy and accurate setting of the compound slide. A 16-tooth gear and dial indicator for screwcutting is fitted as standard, and is clearly visible from the natural operating position. The dial has 4 numbered divisions and 4 sub-divisions.

To cut an even number of threads such as 12 T.P.I. the leadscrew may be engaged at any division on the dial, and for an odd number of threads, such as 13 T.P.I., the leadscrew must only be engaged at numbered divisions. To cut fractional threads such as 11½ T.P.I. the leadscrew must only be engaged at division 1 on the dial.

The dial indicator cannot be used for metric threads. For these the nut is closed on the leadscrew, and the machine reversed by means of a finger tip reversing switch, mounted through the main control lever on the headstock, after each cut and tool withdrawal, bringing the tool back to starting point. The nut remains engaged until the thread is completed. The Switch is only supplied as extra equipment.

APRON

The apron is a double-walled casting accurately machined and all shafts are arranged to have two bearing points.

Feed and screwcutting controls are interlocked to prevent simultaneous engagement and longitudinal and cross feeds are engaged by a positive single lever control action.

Power for both longitudinal and cross feeds is taken from a separate shaft incorporating a simple slipping clutch arrangement at the

gearbox end which effectively guards against possible damage through careless operation and is equally effective in taking care of the heaviest cuts.

The precision leadscrew (4T.P.I. ACME) is used for screw cutting only and the whole apron arrangement is effectively guarded to comply with Factory Safety regulations and requirements.

Direction operating instructions are clearly shown on the metal plates on the apron.


TAILSTOCK

The Tailstock is of rigid design with a large diameter spindle and screw, and is mounted on independent vee and flat surfaces on the bed. The hole in which the spindle slides is honed to very close limits of accuracy.

The spindle, bored No. 4 Morse Taper, is graduated in inches of travel and is locked in position by a hand lever.

Provision is made for the ejection of centres when the spindle is wound right back, and set screws are fitted to enable the tailstock to be set over for taper turning. A zero setting line simplifies resetting.

Rapid locking of the tailstock to the bed is by means of a detachable ring spanner.




THE MOTOR DRIVE

The motor drive is self-contained and to avoid all possibility of motor failure due to chips or coolant splash, the motor is carried at the rear of the headstock base below the chip tray.

The drive is taken to the main drive pulley on the headstock by five $\frac{1}{2}$ " vee belts enclosed in a light alloy end guard.

The standard motor is 5 H.P. 2-Phase or 3-Phase, but D.C. and Single Phase motors are fitted to order at extra cost, the additional cost being dependent on the type of motor and starting equipment required. Provision for motor belt adjustment is provided.




COOLANT UNIT


Coolant may be supplied from a central coolant source or by a Colchester Auxiliary Coolant Unit. This unit is furnished to order only and at extra cost. There is provision on the standard machine in the chip tray for a return of the coolant, through a filter gauze, to the supply source.

The Coolant piping supplied is fully universal, with telescopic piping for feeding the coolant in any position. Spring loaded glands are employed which require no adjustments. A patented ball type shut-off valve permits easy control of the volume

of coolant. The whole unit is designed to eliminate the leakages which are usually associated with coolant systems.

The Colchester unit has a capacity of $5\frac{1}{2}$ gallons.





THE LATHE BED

The Bed is an exceptionally strong casting of the inverted vee type, with elliptical cross ribbing providing great rigidity.

All bed castings are rough machined and naturally aged before finish grinding of all working surfaces.

Once or twice a week the bed surfaces should be wiped with a rag soaked in paraffin to prevent oil stains, and then thoroughly covered with a good grade machine oil to prevent rust formation.

Never use air lines for cleaning the chips from the lathe bed. Their use causes the chips to lodge under sliding members and in openings around moving parts with possible damage to the machine. A strong

air stream will also blow off the protecting oil film and cause rust formation.

On gap bed lathes the removal of the gap block is an easy matter. Simply release and take out our four Allen type screws, and the block is then free to be removed. No dowels are fitted.

To replace Gap. *Thoroughly clean both block and gap location.* This is most important. Replace block and locate screws. Bring saddle up to give rough alignment and tighten screws down lightly.

If the location faces are clean the block can then be re-aligned with a few taps in the required direction with a hide or non-ferrous hammer.

STANDARD EQUIPMENT

One 16" Direct Mounting Face Plate.	Two Centres (one hard, one soft).
One Direct Mounting Catch Plate.	One Centre Bush.
One Travelling Steady Rest.	Five Keys (Hollow Screws).
Two Spanners.	One "C" Key (Spindle Nose Collar).

EXTRA EQUIPMENT

The list below specifies the items of equipment which can be furnished at extra cost. Additional items are included in this list from time to time and we are available to advise you concerning your needs at any time.

- Low volt lighting equipment.
- Auxiliary coolant supply unit.
- Automatic indexing square toolpost.
- Additional direct mounting chucks.
- Additional sets of hard or soft jaws.
- Additional solid centres.
- Backplate for special fixtures.
- Drill chucks.
- Revolving centres.
- Stationary steady.
- Spindle nose collet chuck attachment (2" max. capacity).
- Taper turning attachment.
- Large face plate (Mascot only).
- Electrical reversing switch.

Automatic Indexing Square Toolpost

This is a very strong and rigid toolpost manufactured from a heat treated steel forging. It can be hand indexed into the operating position, and is arranged to carry

four tools or toolholders having a height up to 1 $\frac{1}{4}$ ".


The hand lever moved in an anti-clockwise direction automatically releases the locating plunger. This enables the turret to be swung to the next indexing position by the clockwise movement of the top handle. A further slight movement of this handle after the turret has reached the indexed position effectively locks the turret block to the topslide. It is also possible to swing the turret block into any position without using the indexing mechanism.

The retracting plunger method of indexing enables the turret block to remain on its bottom face thereby effectively preventing chips from lodging on the location face.


These toolposts are accurately bedded onto a special turret slide which can be supplied in place of, or as an extra, to the standard slide.

Backplates

It may be desired to accommodate special fixtures on the Colchester Lathes for turning quantities of parts which can only be



Collet Attachment



Taper Turning Attachment

held in a fixture. Backplates are then necessary and can be supplied made from high grade "Meehanite" castings and machined for direct mounting on the spindle nose of the machine.

Stationary Steady

This attachment is of rigid design and easily opened and set. The maximum bar capacity is 6" dia. and the inserts are of plastic composition and readily replaced.


Spindle Nose Collet Chuck Attachment

This attachment is supplied at extra cost with or without a backplate for direct mounting on the spindle nose of the machine. Its capacity is 2" maximum and any size collet can be supplied up to this diameter.

Chucks

The precision chucks fitted to Colchester Lathes are made from high grade "Meehanite" castings with heat treated nickel-chrome steel scrolls and nickel steel pinions (3-jaw self-centring), and heat treated tough alloy steel jaw operating screws (4-jaw independent), and are all arranged for direct mounting on the lathe spindle nose without the use of backplates. Jaws are dealt with under a separate heading.

When ordering spares it is important to specify the chuck number and size on your order together with the serial number of the machine.



Square Toolpost

Additional Sets of Hard or Soft Jaws

The jaws are made from a special grade of case-hardened steel, accurately machined on all surfaces and all hard jaws are heat treated and ground on bearing and gripping surfaces. When ordering it is important to specify the chuck number and size on your order together with the serial number of the machine.

Taper Turning Attachment


The attachment offers an effective means of producing tapers up to 9° in each direction. It is of simple design, and graduated in both degrees of arc and taper per foot. The length of taper which can be dealt with at one setting is 12".

To operate the attachment, remove fixing screw from cross slide nut and fix in taper turner slide collar. Finally fix and tighten anchor bracket into required position.

Care must be taken to avoid winding the cross slide nut along the traverse screw when the fixing screw has been removed as it might get into a position where movement of the taper slide can foul against it.

Always check that there is no interference by winding the carriage by hand the full length of the taper turning slide.

To revert to normal cross-slide work, remove fixing screw from taper turner slide collar and return to cross slide nut. Finally remove anchor bracket.



Stationary Steady





Diagram illustrating method of Levelling



Main Dimensions

INSTALLATION

Installation and Location

To obtain the full accuracy which has been built into the Colchester Lathe, it is essential that it should be placed on a solid level foundation which is free from vibration.

The best practice is to place the machine on a reinforced concrete base. A wooden floor is not recommended because the swelling and shrinking of the wood, due to atmospheric conditions, causes distortion of the alignment of the machine.

If a wooden floor site cannot be avoided, a section of flooring seven feet long and three feet wide should be removed, and a concrete base built up to the wooden floor level. Holding down bolts should be inserted in this base at proper intervals to fit the drilled holes in the machine legs.

If setting the machine above ground floor level, or on a balcony, cannot be avoided, a reinforced concrete floor is necessary to obtain best results and it is recommended that the Headstock be set as close to supporting walls and pillars as possible.

The machine weighs about 33 cwt. and proper equipment for handling this weight should be available.

After your machine has been unloaded, it should be left on its shipping skids, while it is moved to its location in the machine shop. In certain cases an eye-bolt is supplied ready fixed on the bed of the machine, and this should then be used for lifting purposes.

When the eye-bolt is not supplied, it is recommended that the machine is lifted by means of an adequately strong rope sling inserted through the bed openings. The machine should never be lifted by means of a sling around the outside of the lathe bed, otherwise the lead screw and feed shaft may be distorted.

Cleaning

Before moving any of the slides of your lathe, all machined surfaces should be thoroughly washed with paraffin to clean off the slushing compound used to protect these surfaces, together with any dust or dirt that may have accumulated in transit. This operation is very important as it prevents dirt from working under the sliding members and avoids subsequent undue wear. Care must be taken to ensure that the paraffin is not allowed to remain on the slides and all surfaces must be thoroughly covered with a good grade of machine oil to prevent the formation of rust.

After the machine has been thoroughly cleaned, surfaces lubricated and installed on its foundation, it is ready for levelling and wiring.

Technical Department

Our Technical Department is at your disposal, and always pleased to discuss your particular problem. Our aim is to ensure maximum satisfaction with your Colchester Lathe.

Chuck Mounting

By the use of the American Long Taper Key Drive spindle nose, the danger of chucks and other work holding fixtures becoming loose whilst rotating has been eliminated, but care must be taken to ensure that chucks, etc., are driven home firmly by means of the special key provided with the standard equipment. Both chuck and spindle tapers must be thoroughly cleaned before mounting. It is most important to avoid damaging any part of the spindle nose or chuck taper, as burrs will prevent the chuck being fully tightened.

Levelling

Levelling screws are supplied for both headstock base and rear leg. By adjustment of the headstock and rear leg levelling screws the proper transverse level of the machine can be quickly obtained.

The machine is then levelled longitudinally along the bed at several points, and the adjustment of the headstock or rear leg levelling screws simultaneously quickly gives alignment to the bed.


The holding down bolts should now be secured and another complete check made to ensure that no distortion has taken place. If this levelling has been carefully done with a suitable precision level, the machine will now be ready for use after electrical wiring has been completed.

Turning Tests

The levelling procedure will put the machine into accurate alignment for all normal work, but sometimes turning tests are taken to check alignment and to establish a greater degree of accuracy when the machine is to be employed on Toolroom work.

These turning tests must be taken with keen tools taking a very light cut.

At our plant these tests are taken on two



The above diagrams show Lubrication Points requiring regular attention

discs held 12" apart in a chuck and as shown in sketch. A very light cut is taken on Disc A and B. Micrometer readings of the two discs should be the same. Similarly a bar can equally well be used for this test.




Diagram showing Turning Tests

LUBRICATION

The accuracy and very life of the machine depend on correct lubrication.

The chart on the opposite page provides information regarding the points which require frequent attention, and it cannot be too strongly stressed to the operator that *daily* attention is necessary to ensure efficient functioning of the machine.

When a machine leaves our plant, the Headstock and Feedbox are filled to the proper oil gauge level with the recommended lubricant, Shell Tellus oil 41, a hydraulic type of lubricant conforming to the following specification:

Gravity 60°F.	880	
Flash Point Closed	420°F	
Pour Point	-10°F	
Viscosity Red. No. 1	70°	1300 Sec.
" "	140°	165 "
" "	200°	62 "

and containing inhibitors against oxidation, frothing, and corrosion.

Always stop the machine when checking the oil levels to give the oil an opportunity to settle so that a true reading may be taken. If this is not done overfilling may take place resulting in excessive heat and waste of oil by leakage.

Oil levels should be checked weekly.


Thirty days after the machine goes into operation the headstock and gearbox should be drained, flushed with clean flushing oil and refilled with the recommended oil to the proper levels.

The motor bearings should be checked periodically to see that they are packed with grease of the grade recommended by the manufacturer of the motor on your machine. The coolant pump motor bearings should be checked periodically to see that they are packed with a water repellent grease.


WIRING TO POWER SUPPLY

The wiring should be done by a competent electrician in accordance with the standard diagram provided. The wiring should be of a permanent character, being enclosed in properly supported conduits and complying with all safety regulations and requirements.

It is essential that an efficient means of earthing the machine should be provided.



Wiring Diagram




The Headstock

SPARE PARTS HEADSTOCK

No.	Name of Part	No.	Name of Part
1	Headstock	47	Reverse Shaft Gear 50T/10P
2	" " Cover ..	48	" " Bush ..
3	Front Bearing Outside Cover	49	" " Collar ..
4	Front Bearing Inside Cover	50	Reverse Idler Gear Circlip
5	Back Bearing Outside Cover	51	" " " 38T/10P
6	Back Bearing Inside Cover	52	" " " Shaft ..
7	Inside Screwed Collar ..	53	" " " Bush ..
8	Spindle	54	" " " Washer
9	Spindle Clutch	55	Gear Shifting Shaft for Reverse
10	Front Bearing Peg	56	Gear Shifting Lever ..
11	Large Clutch Gear 104T/10P	57	" " " Pad ..
12	Small Clutch Gear 55T/8P..	58	Reverse Handle
13	Screwed Collar on end of Spindle	59	Face Plate 16" dia. ..
14	Reverse Gear 50T/10P ..	60	Catch Plate
15	Back Bearing Spring thrust ring	61	Spindle Nose Draw Nut ..
16	Large Clutch Gear Keep ..	62	" " " Key ..
17	Large Clutch Gear Keep Screw	63	" " " Key
18	Spindle Clutch Shifter ..	64	Centre
19	Spindle Clutch Shifter Pads (2)	65	Centre Bush
20	Spindle Clutch Shifter Shaft	66	Back Bearing Cover Gasket
21	Spindle Clutch Shifter Shaft Collar	67	Front Bearing Cover Gasket
22	Spindle Clutch Shifter Handle	68	Driving Shaft Bush ..
23	Spindle Clutch Shifter Shaft Collar (back)	69	Domed Washer for Reverse Handle
24	Driving Shaft	70	Filler Plug
25	Driving Shaft Gear 32T & 19T	71	Oil Sight
26	" " " 25T & 38T	72	Front Bearing
27	Driving Shaft Collar ..	73	Back Bearing
28	Second Shaft 16T/10P ..	74	" " Spring
29	" " Gear 41T/8P ..	75	Switch Lever
30	" " " 34T ..	76	Reverse Switch Link ..
31	" " " 28T ..	77	" " Shaft
32	" " " 47T/8P ..	78	" " Lever Collar
33	" " Bush	79	" " Handle Stem
34	Backshaft Gear Shifter Washer	80	Change Gears 36T/10P ..
35	Gear Shifter for Backshaft ..	81	" " 120T/10P ..
36	Gear Shifter Lever (2) ..	82	" " Sleeve
37	Backshaft Gear Shifting Handle	83	" " Stud
38	Gear Shifter Plate	84	" " Nut (3)
39	Locking Disc	85	Change Gear Spacer Collar (2)
40	" " Stud (2)	86	Change Gear Sleeve Stud Nut
41	Locking Piece	87	Swing Frame
42	Locking Disc Plunger (2) ..	88	Change Wheel Sleeve Stud Washer
43	Locking Disc Plunger Spring	89	Oiler for Change Wheel ..
44	Domed Washer for Shifting Handles	90	Oiler Nut for Change Wheel Stud
45	Locking Disc Stud $\frac{1}{2}$ " Hex Nut	91	Driving Pulley
46	Reverse Shaft	92	Brake Shoes
		93	Expanding Lever
		94	Brake Ring Spring ..
		95	Brake Shoe Fixing Stud ..

When ordering spares please give Serial No. of machine, name of unit and Part No.



MASCOT Quick Change Feed Box

SPARE PARTS


HEADSTOCK—continued

No.	Name of Part	No.	Name of Part
96	Flanged Bearing		Nut for Clutch Gear Keep Stud
97	Brake Crank Lever		Head Cover Fixing Screws $\frac{1}{4}$ " x 2" Cap Head
98	Stud for Link		Head Cover Fixing Screws $\frac{1}{4}$ " x 1 $\frac{1}{2}$ " Cap Head
99	Pulley Retaining Washer ..		Spindle End Collar Screw ..
100	Collar on Operating Lever ..		Spindle Inside Collar Screw ..
101	Flanged Bearing Bushes ..		2nd Shaft Bush Plug Screw ..
102	Brake Operating Link		2nd Shaft Gear Screw
103	Operating Handle Stem		Reverse Shifting Shaft Domed Washer Screw ..
104	" " Shaft		Clutch Shifting Shaft Domed Washer Screw ..
105	Switch Lever		Reverse Shaft Screws
106	Adjusting Rod		Reverse Shaft Nut
107	" " Knuckle (RH)		Reverse Shaft Nut Washer Backshaft Gear Shifter Plate
108	" " (LH)		Driving Shaft Collar Screw
109	Washer on Driving Shaft ..		Head Bolting Down Screws $\frac{1}{2}$ " x 1 $\frac{1}{2}$ " Cap Head ..
110	Operating Shaft Spring		Head Bolting Down Screws $\frac{3}{8}$ " x 1 $\frac{1}{2}$ " Cap Head ..
111	Driving Shaft Bearing 'O' Ring		Locking Disc Pins
112	Domed Washer on Clutch Shifting Shaft		Backshaft Lever Domed Washer Screws
113	2nd Shaft Bush		Spindle Nose Key Screws ..
114	Reverse Shaft Oil Seal		Pads for Collar Locking Screws Brass
115	Driving Shaft Oil Seal		Reverse Bush Screws
116	Cam Ring		Reverse Shaft Collar Screw
117	Reverse Switch		Spindle Clutch Shifting Shaft Nut
118	" " Bracket		Spindle Clutch Shifting Shaft Washer
119	" " Cover		Reverse Lever Ball $\frac{1}{4}$ "
120	Operating Shaft Spring Bush		Reverse Lever Spring
121	Clutch Shifting Shaft Handle		Swing Frame Fixing Stud Nut
122	Electric Switch		Clutch Bearing Screws
	Cam Ring Fixing Screws ..		Clutch Adjusting Rod Nut ..
	Drain Plug $\frac{3}{8}$ " Gas		Split Pins for Knuckles ..
	Motor Pulley Slide Rails ..		Switch Lever Pin
	Motor Fixing Bolts		Switch Lever Screw
	Motor Stop Piece		Switch Box Screws
	Fixing Screw for 2nd Shaft		Motor Rail Fixing Screws ..
	Brass Bush		Stop Piece Fixing Screws ..
	Headstock Set-over Screws		Motor Adjusting Screws ..
	Outside Front Bearing Cover Screws		Motor Fixing Bolt Nuts ..
	Outside Back Bearing Cover Screws		Motor Fixing Bolt Washers
	Inside Back Bearing Cover Screws		Belt Guard Plate Screw ..
	Reverse Handle Leather Washer		Switch Box Bracket Screws
	Clutch Handle Leather Washer		
	Spindle Reverse Gear Key		
	2nd Shaft Key No. D. Woodruff		
	Driving Shaft Key No. 21 Woodruff		
	Clutch Shifting Shaft Key No. 15 Woodruff		

MASCOT QUICK CHANGE FEED BOX

1	Feed Box Cover	10	Tumbler Shaft Bush 1 $\frac{1}{4}$ " long
2	Feed Box Top Cover	11	Tumbler Shaft Bush 1 $\frac{1}{2}$ " long
3	Feed Box Tumbler Bearing	12	Lead Screw Bush
4	Driving Shaft Bush 2 $\frac{1}{2}$ " long	13	Driving Shaft Gear 16T 24T/10P
5	Driving Shaft Bush	14	Inter Shaft Gear 32T/10P ..
6	Inter Shaft Bush 1 $\frac{1}{8}$ " long	15	Inter Shaft Gear 24T/10P ..
7	Cone Shaft Bush 2 $\frac{1}{4}$ " long	16	Tumbler Shaft Gear 24T 42T/10P
8	" " 1 $\frac{1}{2}$ " long		
9	Tumbler Bearing Bush		

When ordering spares please give Serial No. of machine, name of unit and Part No.



MASCOT Saddle

SPARE PARTS


MASCOT QUICK CHANGE FEED BOX—continued

No.	Name of Part	No.	Name of Part
17	Tumbler Gear 24T/10P ..	75	Spacer Collar on Driving Shaft ..
18	Inter Shaft 14T/10P ..	76	Knurled Nut on Driving Shaft ..
19	Tumbler Shaft ..	78	Driving Shaft Circlip (External) ..
20	" " Collar ..	79	Spring (Large) ..
21	" " Handle ..	80	$\frac{3}{8}$ " Balls ..
22	" " Socket ..	81	Gasket ..
23	" " Plunger ..	82	Bush for Slipping Clutch ..
24	" " Gear Shaft ..	83	Slipping Clutch Bearing Bush ..
25	Driving Shaft ..	84	Peg for Spring ..
26	Driving Shaft Collar ..	85	$\frac{3}{8}$ " Ball ..
27	Leadscrew Gear Lever ..	86	Feed Shaft Collar ..
28	" " 24T/10P ..	87	Leadscrew Metric Gear Bush ..
29	" " Thrust Sleeve ..	88	Spring (Small) ..
30	Cone Gear Shaft ..	89	Oil Ring for Tumbler Shaft Bearing $2\frac{1}{2}$ " bore ..
31	" " Collar ..	90	Metric Gear Washer ..
32	" " 28T/10P ..	91	Leadscrew Metric Gear 22T/10P ..
33	" " 26T/10P ..	92	Leadscrew Metric Gear Circlip ..
34	" " 24T/10P ..		Gear Shifting Shaft Springs ..
35	" " 30T/10P ..		Gear Shifting Shaft Balls $\frac{1}{2}$ " ..
36	" " 22T/10P ..		Locating Pin Nut $\frac{3}{8}$ " (Hex.) ..
37	" " 20T/10P ..		Leadscrew Gear Lever Pin $\frac{7}{8}$ " x $1\frac{1}{2}$ " Mills ..
38	" " 19T/10P ..		Leadscrew Hand Lever Grub Screw $\frac{7}{8}$ " x $\frac{1}{2}$ " ..
39	" " 18T/10P ..		Top Cover Screws ($\frac{3}{8}$ " x $2\frac{1}{2}$ " ($\frac{7}{8}$ " x $1\frac{1}{2}$ " Cap Hd.)) ..
40	" " 16T/10P ..		Front Cover Screws $\frac{3}{8}$ " x 1" Cap Hd. ..
41	" " Pinion 24T/10P ..		Front Cover Dowel Pin $\frac{3}{8}$ " x $1\frac{1}{2}$ " ..
42 &			Tumbler Bearing Bush Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Cap Hd. ..
43	Gear Shifting Levers ..		Tumbler Arm Screw $\frac{3}{8}$ " x $1\frac{1}{2}$ " Cap Hd. ..
44	" " Pads ..		Feed Box Bush Locating Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc. ..
45	" " Shaft ..		Leadscrew End Collar Grub Screw $\frac{1}{2}$ " x $\frac{3}{8}$ " ..
46	" " Shaft Handle ..		Locating Strip Fixing Screw $\frac{3}{8}$ " x 1" Cap Hd. ..
47	Tumbler Shifting Arm ..		End Plug Grub Screw $\frac{7}{8}$ " x $\frac{1}{2}$ " ..
48	Plug for Tumbler Bearing ..		Feed Shaft Collar and Bush Screw $\frac{7}{8}$ " x $\frac{1}{2}$ " Grub Sc. ..
49	Tumbler for Location Strip ..		Inter Shaft Gear Grub Screw $\frac{7}{8}$ " x $\frac{3}{8}$ " ..
50	Bush for Tumbler Shaft ..		Tumbler Handle Pin $\frac{3}{8}$ " x $1\frac{1}{2}$ " Silver Steel ..
51	Tumbler Locating Pin ..		Cone Shaft Collar Grub Screw $\frac{7}{8}$ " x $\frac{3}{8}$ " ..
52	Tumbler Roller ..		Locating Strip Adjusting Screws $\frac{7}{8}$ " x $\frac{3}{8}$ " Grub Sc. ..
53	Pin for Tumbler Roller ..		Locating Strip Locking Screw $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc. ..
54	Filler Plug ..		Gear Shifting Hand Lever Grub Screws $\frac{7}{8}$ " x $\frac{1}{2}$ " ..
55	Plug for Tumbler Shaft Bush ..		Cone Shaft Gear Key No. 15 Woodruff ..
56	Plug for Inter Shaft Bush ..		
57	Tumbler Handle Spring ..		
59	Gear Shifting Lever Pins $\frac{7}{8}$ " x $1\frac{1}{2}$ " Mills ..		
60	Drain Plug ..		
61	Oil Sight ..		
62	Leadscrew Gear Shifting Shaft ..		
63	Feed Shaft Bearing Bush ..		
64	Tumbler Gear Pin $\frac{7}{8}$ " x $1\frac{1}{2}$ " ..		
65	Tumbler Shaft Circlip (External) ..		
67	Keys for Inter Shaft No. 9 Woodruff ..		
68	Leadscrew Thrust Sleeve Key ..		
69	Leadscrew 8 ft. ..		
69	" " 10 ft. ..		
70	Leadscrew Locknuts ..		
71	" " Plain Collar ..		
72	" " Screwed Collar ..		
73	Feed Shaft 8ft. ..		
73	" " 10 ft. ..		
74	Change Wheel 42T/10P ..		

MASCOT SADDLE

1	Saddle ..	9	Saddle Screw Handwheel Handle ..
2	" " Strip (Back) ..	10	Saddle Screw Nut ..
3	" " " (Front) ..	11	" " Guard ..
4	" " Screw ..	12	" " Locking Screw ..
5	" " " Pinion 12T/10P ..	13	" " Locking Strip ..
6	" " " Keep ..	14	Washer for Saddle Locking Bolt ..
7	" " " Index Ring ..	15	Bottom Slide ..
8	" " " Handwheel ..		

When ordering spares please give Serial No. of machine, name of unit and Part No.



DOMINION Quick Change Feed Box

SPARE PARTS


MASCOT SADDLE—continued

No.	Name of Part	No.	Name of Part
16	Bottom Slide Strip ..		Saddle Nut Fixing Screw
17	Pivot for Swivel Slide ..		Washer ..
18	Topslide ..		Topslide Strip Set-up Screws
19	.. Strip ..		$\frac{3}{16}$ " x $\frac{3}{8}$ " Grub Sc. ..
20	.. Screw ..		Topslide Strip Retaining
21	.. Keep ..		Screws $\frac{3}{16}$ " x $\frac{3}{8}$ " Cap Hd. ..
22	.. Index Ring ..		Bottom Slide Strip Set-up
23	.. Handwheel ..		Screws $\frac{3}{16}$ " x $\frac{3}{8}$ " Grub Sc. ..
24	.. Handwheel Handle ..		Bottom Slide Strip Retain-
25	.. Nut ..		ing Screws $\frac{3}{16}$ " x $1\frac{1}{2}$ "
26	Swivel Slide ..		Cap Hd. ..
27	.. Bolts ..		Travelling Steady Finger
28	Tool Plate ..		Fixing Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub
29	.. Bolt ..		Travelling Steady Finger
30	.. Bolt Nut $\frac{1}{2}$ " ..		Fixing Pads $\frac{1}{2}$ " x $\frac{1}{2}$ " ..
31	.. Screw ..		Back Saddle Strip Screws
32	.. Spring ..		$\frac{1}{2}$ " x 2" ($\frac{7}{16}$ " Hex.) ..
33	Topslide Index Locking		Front Saddle Strip Screws
	Screw ..		$\frac{1}{2}$ " x 2" ($\frac{7}{16}$ " Hex.) ..
34	Saddle Index Locking Screw		Saddle Locking Strip Fixing
35	Saddle Index Locking Pin ..		Screw $\frac{1}{2}$ " x 2" ($\frac{7}{16}$ " Hex.) ..
36	Topslide Screw Self Locking		Apron Fixing Screws $\frac{1}{2}$ " x $1\frac{1}{2}$ "
	Nut $\frac{1}{2}$ " B.S.F. ..		($\frac{7}{16}$ " Hex.) ..
37	Saddle Screw Self Locking		Saddle Keep Fixing Screws
	Nut $\frac{3}{8}$ " B.S.F. ..		$\frac{1}{2}$ " x 2" Cap Hd. ..
38	Saddle Screw Nut Fixing		Saddle Screw Guard Screws
	Screw ..		$\frac{1}{2}$ " x $\frac{3}{4}$ " Cap Hd. ..
39	Ball for Index Rings $\frac{1}{4}$ " ..		Swivel Bolt Nuts $\frac{1}{16}$ " ($\frac{3}{8}$ "
40	Springs for Index Rings ..		Hex.) ..
41	Follow Rest ..		Saddle Oil Screws $\frac{1}{2}$ " x $\frac{3}{8}$ "
42	.. Fingers ..		Countersunk ..
43	.. Finger Tips ..		Saddle Oil Screws $\frac{1}{2}$ " x $\frac{3}{8}$ "
44	.. Screws ..		Topslide Nut Fixing Screw
45	Follow Rest Fixing Screws		$\frac{3}{16}$ " x $\frac{3}{8}$ " Grub Sc. Half
46	Follow Rest Fixing Screw		Dog Pt. ..
	Washers ..		Topslide Keep Screws $\frac{3}{16}$ " x
	Follow Rest Fixing Screw		$\frac{3}{4}$ " Cap Hd. ..
	Nuts ..		Oilers ..

DOMINION QUICK CHANGE FEED BOX

1	Gear Box Cover ..	30	Cone Gear Shaft ..
2	.. Top Cover ..	31	.. Collar ..
3	.. Tumbler Bearing ..	32	.. 28T/10P ..
4	Driving Shaft Bush $2\frac{1}{2}$ " long	33	.. 26T/10P ..
5	Driving Shaft Bush ..	34	.. 24T/10P ..
6	Inter Shaft Bush $1\frac{3}{4}$ " long	35	.. 22T/10P ..
7	Cone Shaft Bush $2\frac{1}{4}$ " long	36	.. 22T/10P ..
8	.. $1\frac{1}{2}$ " long ..	37	.. 20T/10P ..
9	Tumbler Bearing Bush ..	38	.. 19T/10P ..
10	Tumbler Shaft Bush $1\frac{3}{8}$ " long	39	.. 18T/10P ..
11	.. $1\frac{1}{16}$ " ..	40	.. 16T/10P ..
12	Lead Screw Bush ..	41	Cone Shaft Pinion 24T/10P
13	Driving Shaft Gear 16T	42	&
	24T/10P ..	43	Gear Shifting Levers ..
14	Inter Shaft Gear 32T/10P ..	44	.. Pads ..
15	.. 24T/10P ..	45	.. Shaft ..
16	Tumbler Shaft Gear 24T	46	.. Shaft Handle ..
	42T/10P ..	47	Tumbler Shifting Arm ..
17	Tumbler Gear 24T/10P ..	48	Plug for Tumbler Bearing ..
18	Inter Shaft 14T/10P ..	49	Tumbler Location Strip ..
19	Tumbler Shaft ..	50	Bush for Tumbler Shaft ..
20	.. Collar ..	51	Tumbler Locating Pin ..
21	.. Handle ..	52	Tumbler Roller ..
22	.. Socket ..	53	Pin for Tumbler Roller ..
23	Tumbler Handle Plunger ..	54	Filler Plug ..
24	.. Gear Shaft ..	55	Plug for Tumbler Shaft Bush ..
25	Driving Shaft ..	56	Plug for Inter Shaft Bush ..
26	Driving Shaft Collar ..	57	Tumbler Handle Spring ..
27	Leadscrew Gear Lever ..	59	Gear Shifting Lever Pins
28	.. 24T/10P ..		$\frac{3}{16}$ " x $1\frac{1}{4}$ " Mills ..
29	.. Bush ..	60	Drain Plug ..
		61	Oil Sight ..

When ordering spares please give Serial No. of machine, name of unit and Part No.



DOMINION Saddle

SPARE PARTS


DOMINION QUICK CHANGE FEED BOX—continued

No.	Name of Part	No.	Name of Part
62	Leadscrew Gear Shifting Shaft		Leadscrew Hand Lever Grub Screw $\frac{1}{8}$ " x $\frac{1}{8}$ " Grub Sc.
63	Feed Shaft Bearing Bush		Top Cover Screws ($\frac{1}{8}$ " x $2\frac{1}{2}$ " ($\frac{1}{8}$ " x $1\frac{1}{2}$ " Cap Hd.
64	Tumbler Gear Pin $\frac{1}{8}$ " x $1\frac{1}{2}$ "		Front Cover Screws $\frac{3}{8}$ " x $1\frac{1}{2}$ " Cap Hd.
65	Tumbler Shaft Circlip (External)		Front Cover Dowel Pin $\frac{1}{2}$ " x $1\frac{1}{2}$ "
67	Keys for Inter Shaft No. 9 Woodruff		Tumbler Bearing Bush Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Cap Hd.
68	Leadscrew Gear Bush Key		Tumbler Arm Screw $\frac{3}{8}$ " x $1\frac{1}{2}$ " Cap Hd.
69	Leadscrew		Gear Box Bush Locating Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc.
70	Leadscrew Locknuts		Screws End Collar Grub Screw $\frac{3}{8}$ " x $\frac{1}{2}$ "
71	Leadscrew Plain Collar		Locating Strip Fixing Screw $\frac{3}{8}$ " x $1\frac{1}{2}$ " Cap Hd.
72	Leadscrew Screwed Collar		End Plug Grub Screw $\frac{3}{8}$ " x $\frac{1}{2}$ "
73	Feed Shaft		Feed Shaft Collar and Bush Screw $\frac{3}{8}$ " x $\frac{1}{2}$ " Grub Sc.
74	Change Wheel 42T/10P		Inter Shaft Gear Grub Screw $\frac{3}{8}$ " x $\frac{3}{8}$ "
75	Spacer Collar on Driving Shaft		Tumbler Handle Pin $\frac{1}{8}$ " x $1\frac{1}{2}$ " Silver Steel
76	Knurled Nut on Driving Shaft		Cone Shaft Collar Grub Screws $\frac{3}{8}$ " x $\frac{3}{8}$ "
77	Plug for Driving Shaft Inside Bush		Locating Strip Adjusting Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc.
78	Driving Shaft Circlip (External)		Half Dog point
79	Spring (Large)		Locating Strip Locking $\frac{3}{8}$ " x $\frac{1}{2}$ " Grub Sc.
80	$\frac{3}{8}$ " Balls		Gear Shifting Hand Lever Grub Screws $\frac{1}{8}$ " x $\frac{1}{8}$ "
81	Gasket		Leadscrew Spacer Collar Key No. 15 Woodruff
82	Bush for Slipping Clutch		Cone Shaft Gear Key No. 15 Woodruff
83	Slipping Clutch Bearing Bush		
84	Peg for Spring		
85	$\frac{1}{8}$ " Ball		
86	Feed Shaft Collar		
88	Spring (Small)		
89	Oil Ring for Tumbler Shaft Bearing 2 $\frac{1}{2}$ " bore		
	Gear Shifting Shaft Springs		
	Gear Shifting Shaft Balls $\frac{1}{8}$ "		
	Locating Pin Nut $\frac{3}{8}$ " (Hex.)		
	Leadscrew Gear Lever Pin $\frac{1}{8}$ " x $1\frac{1}{2}$ " Mills		

DOMINION SADDLE

1	Carriage	31	Tool Holder Screw $\frac{1}{2}$ " x $2\frac{1}{2}$ " Half Dog ($\frac{1}{2}$ " Sq. Hd.)
2	" Gib (Back)	32	Tool Holder Clamp Plate
3	" Gib (Front)	33	Topslide Index Locking Screw
4	" Screw	34	Carriage Index Locking Screw
5	Carriage Screw Pinion 12T/10P	35	Carriage Index Locking Pin
6	Carriage Screw Keep	36	Topslide Screw Self Locking Nut $\frac{1}{2}$ " B.S.F.
7	" Index Ring	37	Carriage Screw Self-Locking Nut $\frac{3}{8}$ " B.S.F.
8	" Handwheel	38	Carriage Screw Nut Fixing Screw
9	Carriage Screw Handwheel Handle	39	Ball for Index Rings $\frac{1}{2}$ "
10	Carriage Screw Nut	40	Spring for Index Rings
11	" Guard	41	Follow Rest
12	" Locking Screw	42	" " Fingers
13	" Locking Gib	43	" " Tips
14	Washer for Saddle Locking Bolt	44	" " Screws
15	Bottom Slide	45	" " Fixing Screws
16	Bottom Slide Gib	46	" Washers
17	Pivot for Swivel Slide		Saddle Nut Fixing Screw Washer
18	Topslide		Topslide Gib Set-up Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc.
19	" Gib		Topslide Gib Retaining Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Cap Hd.
20	" Screw		Bottom Slide Gib Set-up Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc.
21	" Keep		Bottom Slide Gib Retaining Screws $\frac{3}{8}$ " x $1\frac{1}{2}$ " Cap Hd.
22	" Index Ring		
23	" Handwheel		
24	" Handwheel Handle		
25	" Nut		
26	Swivel Slide		
27	Swivel Slide Bolts		
28	Tool Holder		
29	" Collar		
30	" Swivel Piece		

When ordering spares please give Serial No. of machine, name of unit and Part No.



The Apron

SPARE PARTS


DOMINION SADDLE—continued

No.	Name of Part	No.	Name of Part
	Follow Rest Finger Fixing Screws $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc...		Carriage Screw Guard Screws $\frac{1}{2}$ " x $\frac{3}{8}$ " Cap Hd. ...
	Follow Rest Finger Fixing Pads $\frac{1}{2}$ " x $\frac{1}{2}$ "		Swivel Bolt Nuts $\frac{1}{4}$ " (Hex.) ..
	Back Carriage Gib Screws $\frac{1}{2}$ " x 2" ($\frac{1}{16}$ " Hex.) ..		Carriage Oil Screws $\frac{1}{4}$ " x $\frac{3}{8}$ " Countersunk
	Front Carriage Gib Screws $\frac{1}{2}$ " x 2" ($\frac{1}{16}$ " Hex.) ..		Carriage Oil Screws $\frac{1}{4}$ " x $\frac{3}{8}$ " Countersunk
	Carriage Locking Gib Fixing Screw $\frac{1}{2}$ " x 2" ($\frac{1}{16}$ " Hex.) ..		Topslide Nut Fixing Screw $\frac{3}{8}$ " x $\frac{3}{8}$ " Grub Sc. Half Dog Point
	Apron Fixing Screws $\frac{1}{2}$ " x $1\frac{1}{4}$ " ($\frac{1}{4}$ " Hex.)		Topslide Keep Screws $\frac{1}{8}$ " x $\frac{3}{8}$ " Cap Hd.
	Carriage Keep Fixing Screws $\frac{1}{2}$ " x $\frac{3}{8}$ " Cap Hd.		Oilers


APRON

1	Apron	36	Worm Box Plunger Handle Shaft
2	Leadscrew Half Nut	37	Worm Box Plunger Spring Inter Shaft No. 15 Woodruff Key
3	Locking Piece		Rack Shaft No. 15 Woodruff Key
4	Locking Piece Stud		Racking Shaft No. 9 Woodruff Key
5	Sliding Worm Wheel 55T/10P		Handwheel Domed Washer Screw $\frac{1}{2}$ " x $\frac{3}{8}$ " Cap Hd. ..
6	Surfacing Worm Wheel 46T/10P		Leadscrew Nut Handle Domed Washer Screw $\frac{1}{2}$ " x $\frac{3}{8}$ " Cap Hd.
7	Surfacing Worm Wheel Shaft		Worm Box Handle Shaft Screw $\frac{1}{2}$ " x $\frac{1}{2}$ " Grub Sc. ..
8	Intermediate Wheel 45T/10P		Worm Box Gear Pin $\frac{1}{8}$ " x $2\frac{1}{2}$ " Mills
9	Intermediate Pinion 22T/10P		Safety Strip Stop Screw $\frac{1}{2}$ " x 1" Countersunk
10	Intermediate Shaft		Sliding Worm Wheel Grub Screw $\frac{1}{8}$ " x $\frac{3}{8}$ "
11	Rack Pinion 12T/8P		Surfacing Worm Wheel Grub Screw $\frac{1}{8}$ " x $\frac{3}{8}$ "
12	Racking Pinion 15T/10P		Intermediate Worm Wheel Grub Screw $\frac{1}{8}$ " x $\frac{3}{8}$ "
13	Handwheel Ball Handle		Racking Pinion Pin $\frac{1}{2}$ " x 1 $\frac{1}{2}$ " Mills
14	Worm Box		Dial Indicator Stud Screw $\frac{1}{8}$ " x $\frac{1}{2}$ " Grub Sc.
15	" " Plunger		Dial Indicator Plate Screw $\frac{1}{4}$ " x $\frac{3}{4}$ " Round Hd. Brass ..
16	" " Handle		Dial Fixing and Marking Screws $\frac{1}{2}$ " x $\frac{3}{8}$ " Self Drive
17	" " Pinion 18T/10P		Dial Indicator Guard Screw $\frac{3}{8}$ " x $1\frac{1}{2}$ " (Hex.)
18	Worm Box Worm and Pinion 31T/10P		Leadscrew Handle Stop Screw $\frac{1}{2}$ " x $\frac{3}{8}$ " Cap Hd.
19	Worm Box Worm and Pinion Shaft		Leadscrew Handle Ball $\frac{1}{2}$ "
20	Worm Box Long Spacer		Leadscrew Handle Spring
21	Worm Box Short Spacer		Indicator Guard Pins $\frac{1}{4}$ " x $\frac{1}{2}$ " Mills
22	Leadscrew Nut Ecc. Cam.		Leadscrew Nut Bracket Screws $\frac{1}{2}$ " x $\frac{3}{8}$ " Countersunk ..
23	Leadscrew Nut Handle		Ecc. Cam Shaft Collar Screw $\frac{1}{2}$ " x $\frac{1}{2}$ " Grub Sc. ..
24	Leadscrew Nut Ecc. Cam Collar		
25	Leadscrew Bracket		
26	Ecc. Cam Pin		
27	Handwheel		
28	" Racking Shaft		
29	Dial Indicator Guard		
30	" " Gear		
31	" " Gear Stud		
32	" " Gear Disc		
33	" " Gear Disc Plate		
34	Domed Washer for Leadscrew Nut Handle		
35	Domed Washer for Racking Shaft		

When ordering spares please give Serial No. of machine, name of unit and Part No.



The Tailstock



The Square Turret Toolpost

SPARE PARTS

TAILSTOCK

No.	Name of Part	No.	Name of Part
1	Tailstock	16	Barrel Clamping Bush
2	" Base	17	" " Handle
3	" Barrel	18	Tailstock Set Over Screws $\frac{3}{16}$ " x $2\frac{1}{4}$ " Cap Hd.
4	" " Nut	19	Barrel Clamping Stud Sleeve
5	" Screw	20	Hollow Stud Washer
6	" Keep	21	" " Nut
7	" Handwheel	22	Clamp Stud Nut
8	Domed Washer for Handwheel	23	Ring Spanner
9	Tailstock Handwheel Handle	24	Centre
10	" Barrel Tee Key	25	Locking Handle Stop Pin
11	" Hollow Stud		Tailstock Keep Retaining Grub Screws ($\frac{3}{16}$ " x $\frac{1}{16}$ ")
12	" Clamp Stud		Tailstock Domed Washer Screw ($\frac{1}{4}$ " x $\frac{3}{8}$ " Cap Hd.)
13	" " Plate		Tailstock Set-over Nuts Retaining Grub Screws ($\frac{1}{4}$ " x $\frac{3}{8}$ ")
14	" Set Over Nut		
15	Barrel Clamping Stud		

SQUARE TURRET TOOL POST

1	Square Turret	22	Square Turret Topslide Keep
2	" " Plunger	23	Square Turret Topslide Index Ring Springs
3	" " " Bush	24	Square Turret Topslide Index Ring
4	Square Turret Clamping Screw	25	Square Turret Topslide Handwheel
5	Square Turret Clamping Handle	26	Square Turret Topslide Handwheel Handle
6	Square Turret Cam	27	Square Turret Topslide Nut
7	Square Turret Thrust Washer Cover	28	Square Turret Swivel Slide
8	Square Turret Domed Washer	29	Square Turret Ballsfor Index Rings
9	Square Turret Indexing Cam	30	Square Turret Topslide Screw Locknut
10	Square Turret Plunger Lo- cating Bushes	31	Square Turret Topslide Handwheel Locking Screw
11	Square Turret Bushes Eject- ing Collar	32	Square Turret Clamping Nut Domed Washer Screw $\frac{1}{2}$ " x $\frac{3}{8}$ " Cap Hd.
12	Square Turret Tool Screws		Topslide Strip Set-up Screws $\frac{1}{16}$ " x $\frac{1}{16}$ " Grub Screws
13	Square Turret Top Slide		Topslide Strip Retaining Screws $\frac{1}{16}$ " x $\frac{1}{8}$ " Cap Hd.
14	Square Turret Locating Spring		Topslide Keep Screws $\frac{1}{2}$ " x $\frac{3}{8}$ " Cap Hd.
15	Square Turret Cam Spring		Cam Spring Screws $\frac{1}{16}$ " x $\frac{1}{2}$ " Grub Sc.
16	Square Turret Cam Spring Ball $\frac{3}{8}$ " dia.		Plunger Cam Grub Sc. $\frac{1}{4}$ " x $\frac{3}{8}$ " Grub Sc.
17	Square Turret Thrust Washer W. $1\frac{1}{2}$ "		Plunger Cam Stop Sc. $\frac{1}{2}$ " x $\frac{3}{8}$ " Grub Sc.
18	Plunger Spring		Oilers
19	Location Ball $\frac{3}{8}$ " dia.		
20	Square Turret Top Slide Gib		
21	Square Turret Topslide Screw		

When ordering spares please give Serial No. of machine, name of unit and Part No.

SPARE PARTS

STATIONARY STEADY

No.	Name of Part
1	Stationary Steady
2	" " " Top
3	" " " Loop
4	" " " Fingers
5	" " " Finger Tips
6	" " " Screws
7	Stationary Steady Clamp Plate
8	Stationary Steady Clamp Bolt $\frac{3}{8}$ " x $3\frac{3}{8}$ " ($\frac{1}{8}$ " Hex.) ..
9	Stationary Steady Hinge Bolt $\frac{3}{8}$ " x $1\frac{1}{2}$ " Cap Hd.
10	Stationary Steady Hinge Bolt Nut $\frac{3}{8}$ " Thin

No.	Name of Part
11	Stationary Steady Loop Pin
12	Stationary Steady Loop Screw $\frac{3}{8}$ " x $1\frac{1}{2}$ " ($\frac{1}{16}$ " Hex.) ..
13	Stationary Steady Clamp Bolt Hex. Nut $\frac{3}{8}$ " x $1\frac{1}{2}$ " Deep ($\frac{3}{8}$ " Hex.)
14	Stationary Steady Clamp Bolt Washer $\frac{3}{8}$ " Std.
15	Stationary Steady Finger Locking Screws $\frac{1}{8}$ " x $\frac{3}{8}$ " Grub Screw
	Stationary Steady Locking Screw Pads $\frac{1}{2}$ " x $\frac{1}{2}$ "

TAPER TURNER

1	Taper Turner Bracket
2	" " " Strip
3	Taper Turner "Connecting Slide
4	Taper Turner Slide
5	" " " Bush
6	Taper Turner "Swivelling Plate
7	Taper Turner Plate
8	" " " Slide Strip
9	Anchor Bracket Clamp Plate
10	Anchor Bracket Clamp Plate Bolt $\frac{3}{8}$ " x 2" Hex.
11	Anchor Bracket Clamp Rod
12	Anchor Bracket Clamp Washer $\frac{1}{2}$ " Std.
13	Anchor Bracket
14	Saddle Screw Nut Fixing Bolt
15	Swivelling Plate Screws (2)
16	Swivelling Plate Spigot
17	Saddle Screw Nut Bolt Washer $\frac{1}{2}$ " Std.
18	Anchor Bracket Clamp Rod Washer


19	Anchor Bracket Clamp Plate Rod Nut $\frac{1}{2}$ " Hex.
	Taper Turner Bracket Fixing Screws $\frac{1}{2}$ " x $1\frac{1}{2}$ " Hex.
	Taper Turner Bracket Dowel Pins $\frac{1}{2}$ " x $1\frac{1}{2}$ "
	Taper Turner Bracket Strip Set-up Screws $\frac{1}{8}$ " x $\frac{3}{8}$ " Grub
	Taper Turner Bracket Strip Retaining Screws $\frac{1}{8}$ " x $\frac{3}{8}$ " Cap Hd.
	Taper Turner Slide Set-up Screws $\frac{1}{8}$ " x $\frac{1}{8}$ " Grub Screw
	Taper Turner Slide Retaining Screws $\frac{1}{8}$ " x $\frac{3}{8}$ " Grub Screw
	Taper Turner Connecting Slide Top Fixing Screws $\frac{1}{2}$ " x $1\frac{1}{2}$ " Cap Hd.
	Taper Turner Connecting Slide End Fixing Screws $\frac{1}{2}$ " x $1\frac{1}{2}$ " Cap Hd.
	Spherical Washer
	Dust Cap for Nut Hole

MECHANICAL CLUTCH


1	Clutch Pulley
2	" " Ring
3	" " Bobbin
4	" " Ring Adjusting Screw
5	" " Body
6	" " Flanged Bearing
7	" " " Bush
8	" " Expanding Lever
9	" " Ring Operating Lever
10	" " " Spring
11	" " Fixing Bolt
12	" " Shaft Circlip
13	" " Driving Shaft
14	" " Shifting Fork
15	" " Operating Rod
16	" " Driving Shaft Bush
17	" " Driving Link
18	" " Lever
19	" " Handle Stem
20	" " " Shaft

21	Clutch Pulley Bearing Spacer Ring
22	Clutch Pulley Securing Nut
23	" " Driving Shaft Washer
24	Clutch Driving Shaft Oil Seal
25	Clutch Pulley Bearing Front
26	" " " Back
27	Clutch "Pulley" Bearing Circlip
28	Plastic Knob $1\frac{1}{2}$ " dia. $\frac{3}{8}$ " Whit.
29	Brake Segment
30	Adjusting Screw Nut
	Clutch Driving Link Stud
	Flanged Bearing Retaining Screws (4)
	Operating Lever Screw (1)
	Retaining Washer Screw (1)
	" " Washer Pin (1)


When ordering spares please give Serial No. of machine, name of unit and Part No.



Electrical Equipment



Chuck Spares



Mechanical Clutch

SERVICE HINTS

After several years of use it may be necessary to give attention to various mechanisms and parts which have had extra hard wear and thus tend to cause minor troubles.

Should chatter take place the following points should be observed and given the necessary attention:—

1. See that all slide strips are properly adjusted.
2. Check that there is no lift in the saddle by ensuring that the front and back strips are bedding correctly.
3. Make sure that the Chuck is a good fit on the spindle nose and has not worked loose.
4. The tool should have a keen cutting edge and not be allowed to get dull: see that it is set correctly on the centre line.

Feed Failure

This may be due to the shearing of the shear pin, which can easily be replaced (see page 11) or through the slipping clutch which is housed at the right hand end of the feed box. To adjust this, first release collar on the inside of the tail end bracket and withdraw feed shaft, which will allow the screw in the end to be adjusted, usually a quarter of a turn will be found sufficient.

Lathe not cutting parallel

The lathe bed should be tested for level as described on page 17 and if necessary, the adjustments made. If the gap piece has been removed at any time and has not been correctly replaced this could also be a cause of the trouble when cutting at this end of the bed.

Electric Failure

Points to check:

1. That the Micro Switches are in contact, that is, the tail end cabinet door must be unlocked and the change wheel guard in place.
2. See that the starting switch at the back of the head is working correctly.
3. Check fuses in panel.
4. Check that the three fixing screws in the front of the panel are firmly screwed and that the three pin plug locates in its socket.
5. Panel not holding on, check auxiliary contact on main contactor and any loose connections.

INDEX

GENERAL DESCRIPTION	Page No.	INSTALLATION	Page No.
Headstock	3	Main Dimensions	16
Mascot Quick Change Feed Box	7	Installation and Location	17
Dominion Quick Change Feed Box	8	Cleaning	17
Saddle	11	Levelling	17
Apron	11	Turning Tests	17
Tailstock	12	Lubrication	19
Motor Drive	12	Wiring	19
Coolant Unit	12		
Lathe Bed	13	SPARE PARTS	
Standard Equipment	14	Headstock	21
Extra Equipment	14	Mascot Quick Change Feed Box	23
Square Toolpost	14	Mascot Saddle	25
Backplates	14	Dominion Quick Change Feed Box	27
Stationary Steady	15	Dominion Saddle	29
Collet Attachment	15	Apron	31
Chucks	15	Tailstock	33
Taper Turning Attachment	15	Square Toolpost	33
		Stationary Steady	35
		Taper Turner	35
		Mechanical Clutch	35
		Electrical Equipment	36
		Chuck Spares	36
		Service Hints	37

